




## Trend Memory Write Defect

Affects: ASIC/1-8655

Date: 23 September 2004



Note No. TE-025

A memory write defect has been discovered in trending in all prior versions of the ASIC/1-8655, FW655A1.0 through FW655A1.6. This defect causes excessive writing to Flash Memory when trending is used and will eventually damage the controller's flash memory after about 3 years of continuous operation. Although to date we have not seen any problems in the field, this problem requires your immediate attention.

If the Trend Day of Week is "N/A", then Trend is not enabled. The Factory Default is Trend disabled. Please verify that you do not have it enabled.

- If you do **NOT have trend enabled**, then **No Action is required**.
- If you **HAVE Trend enabled**, then **Immediate Corrective Action is required**.  
Disable Trending or upgrade to FW655A1.7 immediately.

**Failure to disable trending or upgrade firmware will lead to controller failure.**

### ***Disable Trending***

#### **Immediately Disable Trending in the ASIC/1-8655 controllers!**

Set the Trend Day of Week to zero, "N/A." Updated a1-8655.pvs and .tcl files that include a Disable Trend button on the Trend screen are available in the Integrator Center.

You may also issue a Device Global command to set the Trend Day of Week = 0 on all controllers on a local bus. If trending is required by your customer, you must update the firmware.

Download 8655-pvs.zip from the Integrator Center. [http://www.asicontrols.com/integrator/asic\\_1\\_8655/](http://www.asicontrols.com/integrator/asic_1_8655/)  
8655-pvs.zip also contains the latest ASIC1.mdb, and Expert.exe file.

### ***Upgrade Firmware***

New Firmware FW655a17 that corrects the problem is available on the integrator center. Download FlashDev8655.zip from the integrator center. [http://www.asicontrols.com/integrator/asic\\_1\\_8655/](http://www.asicontrols.com/integrator/asic_1_8655/)

FlashDev8655.zip includes the firmware file 655a17a.hex as well as the latest version of FlashDev.exe. It is installed in the c:\ASI\FlashDev\ folder.

Use FlashDev.exe to update the firmware over the RS-485 communication line. You will need to connect to each communication bus. The SINC/3 and ASIC/2 controllers do not presently allow pass-thru of flash download messages.

The new version of FlashDev makes it easier to download new firmware:

It automatically sets the Flash Enable option in the controller.

A list of device addresses can be entered for "batch processing".

Technical Note TN-026 Flash Device describes the operation of the In-Field Flash Programmer.

If you have any further questions please contact: ASI Controls Technical Support [support@asicontrols.com](mailto:support@asicontrols.com), or call 925-866-8808